



KAISER & FRAZER PARTS CORPORATION

Willow Run, Michigan, U.S.A.



PARTS & ACCESSORIES

BULLETIN NO. 21

April 14, 1947

TO ALL DEALERS:
(Except in the State of Texas)

Subject: Steering Wheel, Part No. 201205

Steering Wheel, Part No. 201205, is no longer available, and Part No. 201977 will be supplied on all orders for that part. Therefore, please refer to your Chassis Parts Book, Page 45, Group 14.126, and make the following change:

Mark Steering Wheel, Part No. 201205, "Use Steering Wheel, Part No. 201977, on all jobs".

In order to use Part No. 201977 for replacement of Steering Wheels with horn buttons, the following package is necessary: On Kaiser K-100 up to Serial No. 5121, use Horn Ring Package, Part No. 202277; on Frazer F-47 up to Serial No. 3333, use Horn Ring Package, Part No. 202276.

If replacement is needed for steering wheels equipped with horn ring, order only Steering Wheel, Part No. 201977. No Horn Ring Package is necessary.

Suggested list and net prices are:

<u>Part Number</u>	<u>Part Name</u>	<u>Suggested List Price</u>	<u>Net Price</u>
201977	Steering Wheel	\$6.60	\$4.29
202276	Horn Ring Package (F-47 up to Serial No. 3333)	5.10	3.32
202277	Horn Ring Package (K-100 up to Serial No. 5121)	5.10	3.32

All Prices are F.O.B. Shipping Point and include Federal Excise Tax.
PRICES ARE SUBJECT TO CHANGE WITHOUT NOTICE

Because of field requests for the horn ring installation on early production cars equipped with horn button, we believe this substitution will be very acceptable to your owners.

Sincerely,

Manager

AKSteigerwalt:dh

FOR OWNER SATISFACTION - USE ONLY FACTORY APPROVED PARTS AND ACCESSORIES