



KAISER & FRAZER PARTS CORPORATION

Willow Run, Michigan, U. S. A.



PARTS & ACCESSORIES

BULLETIN NO. 50

October 6, 1947

TO ALL DEALERS:

Subject: Defroster Switch Installation

We have received a number of reports that defroster switches are shorting out due to coming in contact with the radio.

In checking this, we find that the difficulty is caused by the improper installation of the defroster switch. The terminals on the defroster switch are purposely set off center to allow for the proper clearance between the defroster switch terminals and the radio, and if the defroster switch is installed with the terminals pointing toward the rear of the car, there can be no interference with the radio.

Please pass this information along to those in your organization responsible for installing heaters and radios, instructing them to make certain that the defroster switch is properly installed so that when a radio is installed the switch will not come in contact with the radio case.

Sincerely,


Manager

AKSteigerwalt:gr

FOR OWNER SATISFACTION - USE ONLY FACTORY APPROVED PARTS AND ACCESSORIES